## Survey of "Failed" Floor Drains

| Location                                 | Date of Repair |
|--|----------------|
| Basement Public Men's Room               | 6/6/2022       |
| Basement Ladies Locker Room (Right Side) | 6/7/2022       |
| Basement Men's Locker Room (Left Side)   | 6/7/2022       |
| Basement Paint Shop                      |                |
| Basement Front of York Chiller           |                |
| 1st Floor Lockup                         |                |
| 1st Floor Public Woman's Room            | 6/7/2022       |
| 1st Floor Public Men's Room              | 6/7/2022       |
| 1st Floor DC Clerk's Ladies Room         | 6/6/2022       |
| 1st Floor DC Probation Men's Room        |                |
| 3rd Floor Employee Woman's Room          | 6/6/2022       |
| 3rd Floor Public Men's Room              | 6/6/2022       |
| 3rd Floor SC Cerk's Men's Room           |                |
| 4th Floor Public Men's Room              |                |
| 4th Floor Public Woman's Room            |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |
|  |                |